

PURCHASER Sheena Fernandez DATE OF TREATMENT 6-25-25

MAILING ADDRESS _____ LOCATION 3280 Brighton Pl.

CITY _____ STATE _____ ZIP _____ CITY Lexington STATE Ky ZIP 40509

HOME PHONE _____ OFFICE PHONE _____ PHONE (859) 396-8359

I, the property owner agree for Integrity Termite & Pest Management, LLC to undertake the necessary treatment to control the above property for Termites

For the sum of \$ 1400.00, Integrity has agreed with the owner named herewith to service the above described property for five (5) years.

For the additional sum of \$ 175.00, payable each year on or before effective date of further treatments necessary will be performed free. Warranty shall be cancelled if inspection fee is not paid in full each year. Owner also agrees not to store wood or paper under said building and to repair any accumulation of water.

This Agreement does not guarantee against present or future subterranean termite damage nor provide for repairs of compensation therefore.

After the fifth year Integrity reserves the right to revise the annual charge.

This warranty may be extended after the five (5) years, subject to a change in the renewal fee, and being agreeable to both parties.

Additions or alterations to property which in the opinion of Integrity constitutes a subterranean termite hazard, such additions or alterations shall be promptly reported to Integrity and must be serviced as soon as practicable at the expense of the owner or this Agreement shall immediately become null and void.

This Agreement is not valid unless actual work performed, and service charge is paid in full. It is understood and agreed between the parties of this contract that this contract embodies the entire agreement and no covenant or agreement, oral or written, expressed or implied, shall limit, modify or qualify the terms of this contract and its provisions.

Thank you for the opportunity to serve you.

ACCEPTED IN ALL TERMS AND CONDITIONS BY SIGNATURE

Integrity _____

Integrity Representative Sheena Fernandez

Date of Transaction 6-25-25

Purchaser's Signature _____

Date of Transaction X

TYPE OF STRUCTURE Residence Duplex Multi-Family Commercial Other _____

CONSTRUCTION Foundation Material Follow Block Brick Concrete Soil Pre-Treatment for new Construction Other _____


Exterior Veneer Wood Brick Stone Other _____

Type of Chemical Used: 061 Termitol

GRAPH OF PROPERTY

0	5	10	15	20	25	30	35	40	45	50	55	60	65	70	75	80	85
5																	
10																	
15																	
20																	
25																	
30																	
35																	
40																	
45																	
50																	

X = Termites



Special Instructions Termites have damaged drywall in garage and carpet on side of walls, could be hidden and unseen damage. Cannot see behind fixed walls ceilings or insulation. Moisture under carpet on right side of home facing house, track strip is black and rotten

- Basement and Slab
- 1. uncover, drill & treat slab
 - 2. drill treat foundation voids
 - 3. drill treat veneer voids
 - 4. drill treat fireplace voids
 - 5. drill treat partition wall
 - 6. rod and treat soil
 - 7. drill & treat adjoining slabs
 - 8. drill & treat adjoining drive
 - 9. remove termite tunnels
 - 10. make plumbing access
 - 11. make access hole

- Crawl Space
- 12. remove scrap wood
 - 13. trench foundation, treat
 - 14. trench piers, treat
 - 15. remove termite tunnels
 - 16. drill foundation, treat
 - 17. drill piers, treat
 - 18. make access
 - 19. drill, rod exterior slab from crawl
 - 20. rod, trench exterior foundation, treat
 - 21. drill adjacent slab, treat
 - 22. vents

Portion treated House

Price of Treatment \$ 1400.00

Treatment is for Termites only